Standardised navigation | Vehicle | Information media | Tool Management | Subscription

Identification via VIN | Identification via vehicle data | Charging products

WP0ZZZY12LSA66740

Vehicle identification number (VIN)	WP0ZZZY12LSA66740
Order type	Taycan Turbo (Y1AFC1)
Model year	2020

There are open campaigns concerning this vehicle. Please contact your Porsche Centre.

Annotation: The information listed below might not be a complete vehicle history. Only jobs that have been documented within PCSS job management (PQIS) are available. This information may not be transmitted to third parties.
Total warranty repair days (WRD): **248 Day(s)**

Filter settings

Workshop/Recall campaign | OTA campaign | Repair | Maintenance/Inspection | Documentation | Reset Filter

Expand all

Status	Repair Start	Repair End	Dealer	Mileage	DMS order number	
DMS			6000160	0 km	30776	1
Maintenance/Inspection			Minor maintenance: Inspektion			
DMS	11/04/2023		2102084	-	243990	1
Documentation			Warranty check for pre-owned Porsche vehicles: PA + 12 MOIS			
DMS	22/11/2021		2102084	14702 km	230678	1
Repair			**Location:** 91020 Assistance systems central control unit **Symptom:** 1612 Does not function in some cases			
	01/03/2025	01/03/2025	1000001	65543 km		1
OTA campaign			**Location:** WRW11 Re-programming over-the-air (OTA) control unit **Symptom:** 6601 OTA campaign			
DMS	07/01/2025	08/01/2025	2102084	63706 km	261520	5
Campaign			**Location:** Campaign complete: WRE11 Checking high-voltage battery and replacing cell block module if necessary **Symptom:** 6600 Workshop campaign			
Campaign			**Location:** Campaign complete: WPK05 Re-programming PSM control unit **Symptom:** 6600 Workshop campaign			
Campaign			**Location:** Campaign complete: AR808 Replacing brake hose the left and right front axle **Symptom:** 9900 Recall campaign			
DMS	15/04/2024	18/04/2024	2102084	63706 km	254368	1
Repair			**Location:** 51010 Body **Symptom:** 3027 Water stains			
DMS	28/02/2024	28/02/2024	2102084	63067 km	252971	1
Documentation			Warranty check for pre-owned Porsche vehicles			
DMS	06/02/2024	09/02/2024	2102084	62612 km	252228	3
Campaign			**Location:** Campaign complete: WPN82 Re-programming central computer (PCM) control unit **Symptom:** 6600 Workshop campaign			
Campaign			**Location:** Campaign complete: WPS91 Re-programming thermal management control unit (TME) **Symptom:** 6600 Workshop campaign			
Repair			**Location:** B2800 Electric passenger compartment heater **Symptom:** 1611 Broken into pieces			
	18/09/2023	27/09/2023	2220957	55352 km		1
Repair			**Location:** 27080 Cell block module **Symptom:** 1611 No function			
	05/09/2023	08/09/2023	2220889	55352 km		1
Repair			**Location:** 27060 Vehicle electrical system battery **Symptom:** 4072 Voltage too low			
DMS	11/04/2023	12/04/2023	2102084	39153 km	243991	2
Campaign			**Location:** Campaign complete: WNG21 Check rear cover and rework if necessary **Symptom:** 6600 Workshop campaign			
Campaign			**Location:** Campaign complete: WNV01 Re-programming battery sensor control unit and electronic air-conditioning compressor control unit **Symptom:** 6600 Workshop campaign			
DMS	14/06/2022	22/09/2022	2102084	24530 km	235815	4
Campaign			**Location:** Campaign complete: WNU81 Update to software network VR19.0.1 **Symptom:** 6600 Workshop campaign			
Campaign			**Location:** Campaign complete: WNE31 Replacing front seat-belt buckle **Symptom:** 6600 Workshop campaign			
Campaign			**Location:** Campaign complete: ANA52 Reworking wire harness for front seats **Symptom:** 9900 Recall campaign			
Repair			**Location:** 91100 Front PCM display and operator control unit **Symptom:** 1612 Does not function in some cases			
DMS	06/01/2022	04/05/2022	2102084	16775 km	231857	1
Repair			**Location:** 90350 Gateway control unit **Symptom:** 1611 No function			
DMS	07/04/2022	08/04/2022	2102084	16775 km	234191	2
Campaign			**Location:** Campaign complete: WNA51 Re-programming power electronics and engine electronics (DME) **Symptom:** 6600 Workshop campaign			
Repair			**Location:** B2800 Electric passenger compartment heater **Symptom:** 1611 No function			
DMS	25/03/2022	25/03/2022	2102084	16657 km	233893	1
Documentation			Warranty check for pre-owned Porsche vehicles: GARANTIE PORSCHE APPROVED SUR VO 12 MOIS			
DMS	17/08/2021	27/08/2021	2102084	6901 km	228204	3
Campaign			**Location:** Campaign complete: WLK22 Checking electric charge port doors and replacing wire harness if necessary **Symptom:** 6600 Workshop campaign			
Campaign			**Location:** Campaign complete: AMB56 Leistungselektronik neu programmieren **Symptom:** 9900 Recall campaign			
Repair			**Location:** 91520 Central computer **Symptom:** 1614 Function not as specified			
DMS	12/04/2021	21/04/2021	2102084	4764 km	225053	3
Campaign			**Location:** Campaign complete: WMA50 Update software for various control units **Symptom:** 6600 Workshop campaign			
Campaign			**Location:** Campaign complete: WMA71 Perform software update for charger (Porsche Mobile Charger Connect) **Symptom:** 6600 Workshop campaign			
Repair			**Location:** 90250 Instrument cluster **Symptom:** 1611 No function			
DMS	19/08/2020	21/08/2020	2102084	1318 km	219403	4
Campaign			**Location:** Campaign complete: WLE31 Replace vehicle electrical system battery **Symptom:** 6600 Workshop campaign			
Campaign			**Location:** Campaign complete: WLD01 Replace high-voltage line from high-voltage distributor to E-box **Symptom:** 6600 Workshop campaign			
Campaign			**Location:** Campaign complete: WLH61 Check plug connection for water drain hose and connect it correctly if necessary **Symptom:** 6600 Workshop campaign			
Campaign			**Location:** Campaign complete: WL022 Updating software for various control units **Symptom:** 6600 Workshop campaign			
DMS	24/02/2020	12/05/2020	2102084	2 km	216245	7
Campaign			**Location:** Campaign complete: WLB31 Replace ground point for external power connection **Symptom:** 6600 Workshop campaign			
Campaign			**Location:** Campaign complete: WKL62 Supply charging cable **Symptom:** 6600 Workshop campaign			
Campaign			**Location:** Campaign complete: WLC51 Updating software for various control units **Symptom:** 6600 Workshop campaign			
Campaign			**Location:** Campaign complete: WLE11 Check wiper arm screw connection and replace wiper arms if necessary **Symptom:** 6600 Workshop campaign			
Campaign			**Location:** Campaign complete: WLB01 Supply 7.5-metre vehicle charging cable **Symptom:** 6600 Workshop campaign			
Campaign			**Location:** Campaign complete: WLB11 Remove adapter cable in left fuse box **Symptom:** 6600 Workshop campaign			
Campaign			**Location:** Campaign complete: WKK03 Replace and re-teach remote control (hand-held transmitter) **Symptom:** 6600 Workshop campaign			

Vehicle information

Show vehicle information

Show vehicle history