

Cash Invoice

Invoice Name & Address [REDACTED]		Account No. [REDACTED]	Driver Name & Address [REDACTED]	
		Date & Tax Point 17/09/2024		
		Order Number		
Make & Model	Chassis No.	Engine No.	Mileage	Time Page
Taycan GTS (MY23)	[REDACTED]	0	25444	10:41 1
Reference No.	Reg No.	Reg Date.	VS# No.	W.I.P. No. Job No.
	[REDACTED]	29/12/2022		[REDACTED]

	Description of Goods / Services	Qty.	Unit Price	Unit Des.	Net Total	V
A	03180000 Inspection . Replaced pollen filter				327.00	S
A	03402550 Smart Service values programmed Smart Service Values Program Every 20K Miles / 30K Kms or every 2 Years				9.00	S
X	P9A7819429A Dust and pollen filt	1.00	67.42	EACH	67.42	S
X	P00004400204 WINDOW CLEANER OUTER	1.00	9.17	EACH	9.17	S
				Subtotal:	412.59	
A	03510060 Carried out brake fluid service				153.00	S
X	P00004321082 1 Litre Brake fluid	1.00	19.66	EACH	19.66	S
				Subtotal:	172.66	
Z	GT29 YOUR TECHNICIAN TODAY WAS STEPHEN WARD				0.00	Z
				Subtotal:	0.00	
Z	FOL Carried out complimentary wash and vacuum. Carried out inspection in dedicated bay. Your service advisor will be in touch to follow				0.00	S

E & O. E.

V	Rate	Service/Goods	V.A.T.

Customer's Signature

Date

Time

Cash Invoice

Invoice Name & Address		Account No.	Driver Name & Address		
[REDACTED]		[REDACTED]	[REDACTED]		
		Date & Tax Point 17/09/2024			
		Order Number			
Make & Model	Chassis No.	Engine No.	Mileage	Time	Page
Taycan GTS (MY23)	[REDACTED]	0	25444	10:41	2
Reference No.	Reg No.	Reg Date.	VSB No.	W.I.P. No.	Job No.
	[REDACTED]	29/12/2022		[REDACTED]	

Description of Goods / Services	Qty.	Unit Price	Unit Des.	Net Total	V
up on your visit. We hope we exceeded your expectations?					
			Subtotal:	0.00	
Any Queries Please Contact: Robert Derkatsch					

E. & O. E.		V	Rate	Service/Goods	V.A.T.		
Parts	96.25	S	20.00	585.25	117.05	Net	585.25
Surcharge	0.00					V.A.T.	117.05
Lab/Oil/Tyres	489.00					Total	702.30
Sublet	0.00					Paid	0.00
Menus	0.00					Owing	702.30

Customer's Signature Date Time

Head Office & Registered Office:
 Porsche Retail Group Ltd, Bath Road, Calcot, Reading, Berkshire RG31 7SG.
 Reg No. 220221. VAT No. 479410133

Authentic Porsche branded products purchased in the United Kingdom from authorised Porsche Centres, authorised Porsche Service Centres and other legitimate resellers are imported into the United Kingdom by Porsche Cars Great Britain Limited whose registered office is located at Bath Road, Reading, Berkshire, United Kingdom RG31 7SE.

Taycan Check

Porsche Centre Guildford

01483 408 800



PORSCHE

Customer Name [REDACTED]

Contact Telephone Number [REDACTED]

Date 16/09/2024 14:45:07

Wip Number [REDACTED]

Reg. Number [REDACTED]

Vehicle Taycan GTS (MY23)

Mileage 25,555

MOT Due 28/12/2025

Service Due 17/09/2026

Comments/Recommendations

Fitted Price
Inc Vat

Auth

STEP 1: Additional Service Items

G Brake Fluid

G Air Bag Check

R Aircon Service

Aircon Service recommended every 2 years. Includes re-gassing the system to ensure maximum efficiency, injecting a dye to help detect any future leaks and a disinfectant which helps kill bacteria in the ducting and improve the smell of the interior.

N

R Ducts and Drains

Recommend Additional work for water drains check Front, Check and clean to prevent any water ingress, as if any control units fail due to water ingress this would not be covered under the extended warranty

N

R Ducts and Drains

Door sill, Check and clean to prevent any water ingress, includes replacing door sill bungs and replacing high voltage battery drain bungs

N

G Air Filter Due

STEP 2: External Inspection

G Bodywork

G Trim

G Glass

G Mirrors/mirror housing

G Lights

G Washers and Wipers

G Door Locking

G Number Plate Condition

G Charge Points

STEP 3: Tyre Check

A Left Front Tyre

5.0 MM

N

A Right Front Tyre

4.8 MM

N

G Left Rear Tyre

5.8 MM

G Right Rear Tyre

6.1 MM

G Spare or Tyre Inflation Kit

Canister - OK EXP: 01-10-2026

G Wheel alignment recommended?

STEP 4: Under Bonnet

G Coolant Level & Condition

G Battery Condition 12V

G Screen wash Level

G Visible High Voltage Component Security Check

Checked and OK

G Other/miscellaneous

This work has been brought to my attention and I have decided not to have all the work completed before leaving the premises.

Advisor Robert Derkatsch

Customer Signature _____

Inspected by Stephen Ward

Quality Control By Stephen Ward

Date _____

This is not an invoice (all estimates are valid for 30 days). This is a report on mechanical condition, not an invoice or quote for work to be done. Please ask for a written estimate for remedial work.

Taycan Check

Porsche Centre Guildford

01483 408 800



PORSCHE

Customer Name [REDACTED]

Contact Telephone Number [REDACTED]

Date 16/09/2024 14:45:07

Wip Number [REDACTED]

Reg. Number [REDACTED]

Vehicle Taycan GTS (MY23)

Mileage 25,555

MOT Due 28/12/2025

Service Due 17/09/2026

Comments/Recommendations

Fitted Price
Inc Vat

Auth

STEP 5: Internal Check

- G Windscreen and Headlight wash/wipe operation
- G Horn
- G Interior Lights
- G Instruments
- G Foot and Handbrake operation
- G Warning Lights
- G Seat belts/buckles
- G Heating and Ventilation
- G Other/miscellaneous
- G Exterior light operation
- G Cooling fans operation check


STEP 6: Underbody Checks

- G Final Drive Check
- G Steering and Suspension
- G Visually inspect under trays Checked and OK
- G Visually inspect HV battery - protection cover Checked and OK
- G Visually inspect brake hoses Checked and OK
- G Front Brake Disc Thickness 1.6mm before max wear
- G Front Brake Pads Thickness Pads 8 mm remaining
- G Rear Brake Disc Thickness 1.7mm before max wear
- G Rear Brake Pads Thickness Pads 7 mm remaining

- R Other/miscellaneous B147A18 - Radio key 2 – voltage too low, requires remote key battery. N
- R Other/miscellaneous U15AD00 - Quick battery charging (DC), Charging station incompatible, passive fault stored, has happened on 4 occasion. N
- R Other/miscellaneous Electric interior heater (HV-PTC): Production date 15.08.22, requires new heater Warranty 2,385.08 Y

Step 7: QA Test Drive

- Levels Correct **Not Inspected**
- Work Complete **Not Inspected**
- Handling & Performance **Not Inspected**



- Dents
- Scratches
- Chips
- Rust
- Corrosion
- Other

Important: This report is the result of a visual inspection only. Further checks or disassembly may be required to determine the full extent of requirements.

Total price for authorised work 2,385.08

This work has been brought to my attention and I have decided not to have all the work completed before leaving the premises.

Advisor Robert Derkatsch

Customer Signature _____






Inspected by Stephen Ward Quality Control By Stephen Ward

Date _____

This is not an invoice (all estimates are valid for 30 days). This is a report on mechanical condition, not an invoice or quote for work to be done. Please ask for a written estimate for remedial work.

Your tyres.

Reg No: XXXXXXXXXX

Tyres		What does this mean?		Visually OK	Advisory	Immediate attention			
Left Front Tyre		Right Front Tyre		Left Rear Tyre		Right Rear Tyre		Spare or Tyre Inflation Kit	
% worn	5 mm	% worn	4.8 mm	% worn	5.8 mm	% worn	6.1 mm		
✓ pressure checked		✓ pressure checked		✓ pressure checked		✓ pressure checked			
5 inner tread depth		4.8 inner tread depth		5.8 inner tread depth		6.1 inner tread depth			
5.7 middle tread depth		5.4 middle tread depth		6 middle tread depth		6.2 middle tread depth			
5.4 outer tread depth		5.3 outer tread depth		6.4 outer tread depth		6.6 outer tread depth			
Comments	NFO Rated	Comments	NFO Rated	Comments	NFO Rated	Comments	NFO Rated	Comments	Canister - OK

Please note: This report and any repair costs shown are the result of a visual inspection only. Further checks may be necessary to determine the full extent of any requirements. Parts subject to wear are considered defective when the maximum amount of wear permissible is reached.



Tyre labelling

What does it all mean?


All tyres now come with a label that gives ratings for fuel efficiency, wet grip and rolling noise. In the case of fuel efficiency, a rating of A indicates the most efficient and G the least. For wet grip, a tyre with an A rating provides the shortest braking distance and G, the longest. Finally, external rolling noise is measured in decibels. One wave indicates a quieter tyre and three waves are louder (when comparing identical section widths).

Left Front Tyre / Right Front Tyre


Option 1
GOODYEAR
 265/35R21 101Y C
 £385.96

Rating: **B**



Rating: **71 dB**



2009/... - C1











Cost Breakdown

Please review the items listed below and authorise work that you'd like carried out on your vehicle.

● Visually Ok ● Advisory ● Urgent ● Not Checked

✕ Condensed Report

Identified Work			
Item	Status	Price	Include
☰ STEP 1: Additional Service Items			
Brake Fluid	●	-	-
Air Bag Check	●	-	-
Aircon Service <i>Inspection Notes: Aircon Service recommended every 2 years. Includes re-gassing the system to ensure maximum efficiency, injecting a dye to help detect any future leaks and a disinfectant which helps kill bacteria in the ducting and improve the smell of the interior.</i>	●	£325.00	<input type="checkbox"/>
Ducts and Drains <i>Inspection Notes: Recommend Additional work for water drains check Front, Check and clean to prevent any water ingress, as if any control units fail due to water ingress this would not be covered under the extended warranty</i>	●	£279.36	<input type="checkbox"/>
Ducts and Drains <i>Inspection Notes: Door sill, Check and clean to prevent any water ingress, includes replacing door sill bungs and replacing high voltage battery drain bungs</i>	●	£494.70	<input type="checkbox"/>
Air Filter Due	●	-	-
☰ STEP 2: External Inspection			
Bodywork	●	-	-
Trim	●	-	-
Glass	●	-	-
Mirrors/mirror housing	●	-	-
Lights	●	-	-
Washers and Wipers	●	-	-
Door Locking	●	-	-
Number Plate Condition	●	-	-
Charge Points	●	-	-
☰ STEP 3: Tyre Check			

STEP 3: Tyre Check			
Left Front Tyre <i>Inspection Notes: 5.0 MM</i>		£385.96	<input type="checkbox"/>
Right Front Tyre <i>Inspection Notes: 4.8 MM</i>		£385.96	<input type="checkbox"/>
Left Rear Tyre 5.8 MM		-	-
Right Rear Tyre 6.1 MM		-	-
Spare or Tyre Inflation Kit <i>Canister - OK EXP: 01-10-2026</i>		-	-
Wheel alignment recommended?		-	-
STEP 4: Under Bonnet			
Coolant Level and Condition		-	-
Battery Condition 12V		-	-
Screen wash Level		-	-
Visible High Voltage Component Security Check <i>Checked and OK</i>		-	-
Other/miscellaneous		-	-

STEP 5: Internal Check			
Windscreen and Headlight wash/wipe operation	●	-	-
Horn	●	-	-
Interior Lights	●	-	-
Instruments	●	-	-
Foot and Handbrake operation	●	-	-
Warning Lights	●	-	-
Seat belts/buckles	●	-	-
Heating and Ventilation	●	-	-
Other/miscellaneous	●	-	-
Exterior light operation	●	-	-
Cooling fans operation check	●	-	-

STEP 6: Underbody Checks			
Final Drive Check	●	-	-
Steering and Suspension	●	-	-
Visually inspect under trays Checked and OK	●	-	-
Visually inspect HV battery - protection cover Checked and OK	●	-	-
Visually inspect brake hoses Checked and OK	●	-	-
Front Brake Disc Thickness 1.6mm before max wear	●	-	-
Front Brake Pads Thickness Pads 8 mm remaining	●	-	-
Rear Brake Disc Thickness 1.7mm before max wear	●	-	-
Rear Brake Pads Thickness Pads 7 mm remaining	●	-	-
Check and Confirm Tyre Condition	●	-	-
Other/miscellaneous Inspection Notes: B147A18 - Radio key 2 – voltage too low, requires remote key battery.	●	£60.70	<input type="checkbox"/>
Other/miscellaneous Inspection Notes: U15AD00 - Quick battery charging (DC), Charging station incompatible, passive fault stored, has happened on 4 occasion.	●	-	-
Other/miscellaneous Inspection Notes: Electric interior heater (HV-PTC): Production date 15.08.22, requires new heaterWarranty	●	£2,385.08	<input type="checkbox"/>
Cost of Work Selected			£0.00