

WFOZZY12N6A57877



Vehicle identification number (VIN) WFOZZY12N6A57877
 Order type Nissan GT-R (R35) (1+M&E1)
 Model year 2022

There are open campaigns concerning this vehicle. Please contact your Porsche Centre.

Annotation: The information listed below might not be a complete vehicle history. Only jobs that have been documented within PCSS job management (PJM) are available. This information may not be transmitted to third parties. Total security near days (VMS): 48 Days

Filter settings

Workshop/Recall campaign
 OTA campaign
 Repair
 Maintenance/Inspection
 Documentation
 Reset filter

Status	Repair Start	Repair End	Dealer	Mileage	DMS order number	Expand all
11/11/2024	12/11/2024	23/10/10	48214 km	202409929	<ul style="list-style-type: none"> Campaign <ul style="list-style-type: none"> Location: Campaign complete Symptom: ABS/ESC Replacing brake lines the left and right front axle Campaign <ul style="list-style-type: none"> Location: Campaign complete Symptom: WFN625 Re-programming PCM control unit Campaign <ul style="list-style-type: none"> Location: Campaign not feasible Symptom: WRS022 Checking HV/B cell modules and re-programming BMCo software 	
30/10/2024	11/11/2024	23/10/10	48156 km	202409879	<ul style="list-style-type: none"> Campaign <ul style="list-style-type: none"> Location: Campaign not feasible Symptom: WRS022 Checking HV/B cell modules and re-programming BMCo software Campaign <ul style="list-style-type: none"> Location: Campaign not feasible Symptom: ABS/ESC Campaign <ul style="list-style-type: none"> Location: Campaign not feasible Symptom: WFN625 Re-programming PCM control unit Repair <ul style="list-style-type: none"> Location: 27170 High-voltage charger Symptom: 16.13 No function occasionally Repair <ul style="list-style-type: none"> Location: 62000 Electric passenger compartment heater Symptom: 16.13 No function occasionally 	
20/06/2024	20/06/2024	23/10/10	38346 km	202404463	<ul style="list-style-type: none"> Campaign <ul style="list-style-type: none"> Location: Campaign not feasible Symptom: ABS/ESC Campaign <ul style="list-style-type: none"> Location: Campaign complete Symptom: WPL81 Replacing electric passenger compartment heater 	
14/12/2023	14/12/2023	23/10/10	29971 km	202309473	<ul style="list-style-type: none"> Campaign <ul style="list-style-type: none"> Location: Campaign not feasible Symptom: WFN625 Re-programming central computer (PCM) control unit Maintenance/Inspection <ul style="list-style-type: none"> Location: Minor maintenance 	
14/12/2023	14/12/2023	23/10/10	29971 km	202309474	<ul style="list-style-type: none"> Campaign <ul style="list-style-type: none"> Location: Campaign complete Symptom: WFN625 Re-programming central computer (PCM) control unit 	
10/07/2023	10/07/2023	1000001	-	-	<ul style="list-style-type: none"> OTA campaign <ul style="list-style-type: none"> Location: WFN021 Software update for high-voltage battery control unit Symptom: 66011 OTA campaign 	
10/11/2022	16/11/2022	23/10/10	4011 km	202208086	<ul style="list-style-type: none"> Repair <ul style="list-style-type: none"> Location: 55400 Side section flap Symptom: 1622 Does not close 	
04/08/2022	24/08/2022	23/10/10	1272 km	202206422	<ul style="list-style-type: none"> Campaign <ul style="list-style-type: none"> Location: Campaign complete Symptom: WSN611 Update to software network V819.0.1 Repair <ul style="list-style-type: none"> Location: 58220 Front lid Symptom: 9734 Customer complaint cannot be reproduced 	
04/07/2022	06/07/2022	23/10/10	10 km	202205036	<ul style="list-style-type: none"> Documentation <ul style="list-style-type: none"> Location: General workshop visit / Service (DMS): '0' rev. 	

Vehicle information

- Show vehicle information
- Show vehicle history